

**Office of Telephone Exchange
Bahauddin Zakaryia University**

The Purchase Officer,
Bahauddin Zakariya University, Multan



Subject: - REPAIRING/ MAINTENANCE

Sir,

It is stated that Main Board Digital PABX System cards like link cards and extension cards need some repair by the fluctuations of electricity due to high stored live wire.

The details of the estimation is as under

Sr No	Description	Quantity
1	Main Board Digital PABX System (240 ports)	02
2	TLS Card (04+12)	02

It is therefore requested that the case is submitted to the Purchase Officer. The expenditure is met out from the Telephone Exchange of Telephone Exchange budget 2020-21.

Thanking you!

Yours Sincerely,


(Muhammad Zulfiqar)